

Boiler Inspections for TAC RMP Property Members

Texas Association of Counties Risk Management Pool (TAC RMP) recognizes that proper risk control measures are needed to protect county resources. One important infrastructure component for water and heating in counties are boilers. Many things can go wrong with boilers due to the complexity of these systems. Poor maintenance and even failure can lead to expensive repairs and in extreme cases lead to severe damage to buildings and possible injuries to employees and the general public. Through TAC RMP's collaborative relationship with members, we can provide assistance with the rigorous state inspection requirements for boilers and other pressurized vessels you may have in use as well as help in preventing these types of losses. Through state-required inspections and recommended maintenance practices, TAC RMP and its members can protect county resources.

No Cost Boiler Inspections

In partnership with TAC RMP providers, Hartford Steam Boiler Inspection and Insurance Company (HSB) assists Property members with state-required boiler inspections at no cost. HSB was founded in 1866 and is the largest single provider of boiler and pressure vessel-related inspection services in North America. Their extensive knowledge of these systems provides significant value to ensuring your boilers not only meet state requirements but also provide recommendations to ensure reliable and efficient operation for the life of these systems.

Need to schedule an inspection?

HSB maintains a comprehensive list of boilers requiring inspections and will contact members to schedule an inspection prior to expiration of the unit's certificate. TAC RMP members can also request inspection by contacting the HSB Inspection Hotline.

Phone: (800) 333-4677

Email: NSCINSP_HOTLINE@HSB.COM

Fax: (800) 298-4083

Additional information needed for your inspection request:

AIG Policy Number: BOWPN1800281

HSB Policy Number: 2319702

Policyholder: County Reinsurance, Limited (CRL)

Click [here](#) to download the HSB inspection request form.

Boiler Regulatory Agency: Texas Department of Licensing and Regulation

The Texas Department of Licensing and Regulation (TDLR) is the state agency tasked with licensing and regulation of boilers and pressurized vessels. Once a boiler has been inspected, HSB will submit a recommendation to TDLR for issuance of a new inspection certificate. An

invoice will be sent to the member and payment can be submitted with a payment via US mail or paid at TDLR's online payment page by logging into your [account](#). An account must be created before payment can be submitted through the payment page. To create an account, click [here](#).

Click [here](#) to learn more about TDLR and general information concerning boilers and boiler safety.

If you have any specific questions or would like additional information or have questions about boilers, please contact your Risk Control Consultant. You can find a link to your consultant team by clicking [here](#).